

Table 2.4c: Percentage distribution of *partially damaged housing units (usable)*, which did not have drinking water facility after Tsunami by reason for not having water by affected DS divisions* of : Ampara District

Affected DS Division	Reason for not having drinking facilities					Total	
	Well polluted	Main line destroyed	Other	NS [□]	No.	%	
	%	%	%	%			
Kalmuni	92.1	0.8	6.6	0.5	3106	100.0	
Sainthamaruthu	86.8	1.5	11.0	0.7	1578	100.0	
Karathivu	96.0	-	2.4	1.6	663	100.0	
Ninthavur	92.7	1.4	5.5	0.4	928	100.0	
Addalachchenai	85.1	0.9	12.2	1.8	424	100.0	
Akkaraipattu	82.5	1.0	13.6	2.9	686	100.0	
Alayadiwembu	90.7	-	7.4	1.9	66	100.0	
Thirukkovil	87.9	-	11.1	1.0	680	100.0	
Pothuvil	70.9	0.7	22.8	5.6	679	100.0	
Lahugala	100.0	-	-	-	26	100.0	
Total	89.2	0.9	8.8	1.1	8836	100.0	

Source: Department of Census and Statistics

Note: NS[□] - Not Stated

* Statistics given here are only for the affected DS divisions

** Damaged – Completely damaged, Partially damaged (Unusable), Partially damaged (Usable) building units only were considered damaged.