

Table 1.10 : Distribution of damaged housing units in the affected GN divisions by type of damage and distance to the sea : Manmunai Pattu DS Division of Batticaloe District

Affected GN Division	Completely Damaged				Partially damaged (Unusable)				Partially damaged (Usable)				Total			
	Within or on the 200m boundary line	Outside the 200m boundary line	Not Identified	Total	Within or on the 200m boundary line	Outside the 200m boundary line	Not Identified	Total	Within or on the 200m boundary line	Outside the 200m boundary line	Not Identified	Total	Within or on the 200m boundary line	Outside the 200m boundary line	Not Identified	Total
Kirankulam (N)	0	4	0	4	0	12	0	12	0	18	0	18	0	34	0	34
Kirankulam (S)	0	43	0	43	0	12	0	12	0	101	0	101	0	156	0	156
Kirankulam	0	2	0	2	0	14	0	14	0	78	0	78	0	94	0	94
Kirankulam (C)	0	15	0	15	0	28	0	28	0	49	0	49	0	92	0	92
Puthukudiruppu	0	73	0	73	0	47	0	47	0	71	0	71	0	191	0	191
Puthukudiruppu (S)	1	46	0	47	0	52	0	52	0	109	0	109	1	207	0	208
Puthukudiruppu (N)	0	114	0	114	0	31	0	31	0	148	0	148	0	293	0	293
Palamunai	38	126	0	164	19	92	0	111	6	238	0	244	63	456	0	519
Vedarkudiruppu	0	0	0	0	0	0	0	0	0	76	0	76	0	76	0	76
Selvanagar East	0	93	0	93	0	79	0	79	0	205	0	205	0	377	0	377
Arayampathi East	0	78	0	78	0	54	0	54	0	166	0	166	0	298	0	298
D.S. Div. Total	39	594	0	633	19	421	0	440	6	1259	0	1265	64	2274	0	2338

Source: Department of Census and Statistics