

Table 1.3 : Distribution of damaged housing units in the affected DS divisions by type of damage and distance to the sea : Batticaloe District

Affected DS Division	Completely Damaged					Partially damaged (Unusable)					Partially damaged (Usable)					Total				
	Within or on the 200m boundary line	Outside the 200m boundary line	Not Identified	Not available	Total	Within or on the 200m boundary line	Outside the 200m boundary line	Not Identified	Not available	Total	Within or on the 200m boundary line	Outside the 200m boundary line	Not Identified	Not available	Total	Within or on the 200m boundary line	Outside the 200m boundary line	Not Identified	Not available	Total
Koralaipattu North	212	1095	0	0	1307	7	246	0	0	253	1	188	0	-	189	220	1529	0	-	1749
Koralaipattu	127	482	1	-	610	18	146	0	-	164	0	560	0	-	560	145	1188	1	-	1334
Koralai Pattu South	15	28	0		43	13	4	0	-	17	2	5	0	-	7	30	37	0	-	67
Eravupattu	30	69	0	0	99	2	9	0	0	11	1	270	0	-	271	33	348	0	-	381
Manmunai North	377	545	0	36	922 ⁺	20	393	0	74	413 ⁺	1	1399	0	102	1400 ⁺	398	2337	0	212	2735 ⁺
Kattankudy	195	310	0	0	505	37	168	0	0	205	24	1031	0	-	1055	256	1509	0	-	1765
Manmunai Pattu	39	594	0	0	633	19	421	0	0	440	6	1259	0	-	1265	64	2274	0	-	2338
Manmunai South & Eruvil pattu	302	1026	4	0	1332	16	362	0	0	378	5	1575	0	-	1580	323	2963	4	-	3290
District Total	1297	4149	5	36	5451⁺	132	1749	0	74	1881⁺	40	6287	0	102	6327⁺	1469	12185	5	212	13659⁺

Source: Department of Census and Statistics

Note : ⁺ Total is given only for covered areas