

Table 2.1b: Percentage distribution of *partially damaged housing units (unusable)* in affected DS divisions* by highest height submerged by sea water : Batticaloe District

Affected DS Division	Highest height submerged (feet)							Total	
	Less than or equal to 5	6 - 7	8 - 10	11 - 20	21 - 30	More than 30	NS [□]	No.	%
	%	%	%	%	%	%	%		
Koralai Pattu North	50.0	24.0	12.8	12.6	0.2	0.2	0.2	253	100.0
Koralai Pattu	59.4	12.4	4.7	22.6	0.9	-	-	164	100.0
Koralai Pattu South	70.6	17.6	11.8	-	-	-	-	17	100.0
Eravur Pattu	81.8	18.2	-	-	-	-	-	11	100.0
Manmunai North	38.8	22.1	22.7	16.2	-	-	0.2	487	100.0
Kattankudy	41.9	23.4	25.5	8.7	-	-	0.5	205	100.0
Manmunai Pattu	64.4	22.0	6.4	6.9	-	-	0.3	440	100.0
Manmunai South & Eruvilpattu	38.3	17.9	31.4	12.4	-	-	-	378	100.0
Total	46.5	21.0	19.6	12.6	0.1	-	0.2	1955	100.0

Source: Department of Census and Statistics

Table 2.1c: Percentage distribution of *partially damaged housing units (usable)* in affected DS divisions* by highest height submerged by sea water : Batticaloe District

Affected DS Division	Highest height submerged (feet)						Total	
	Less than or equal to 5	6 - 7	8 - 10	11 - 20	21 - 30	NS [□]	No.	%
	%	%	%	%	%	%		
Koralai Pattu North	80.1	6.7	9.7	2.9	0.2	0.4	189	100.0
Koralai Pattu	92.3	3.8	0.3	3.4	-	0.2	560	100.0
Koralai Pattu South	100.0	-	-	-	-	-	7	100.0
Eravur Pattu	98.3	0.9	0.4	-	-	0.4	271	100.0
Manmunai North	82.8	10.4	6.1	0.3	-	0.4	1502	100.0
Kattankudy	80.1	14.2	4.7	0.7	-	0.3	1055	100.0
Manmunai Pattu	84.6	9.1	4.9	1.0	0.1	0.3	1265	100.0
Manmunai South & Eruvilpattu	84.9	9.0	4.5	1.1	-	0.5	1580	100.0
Total	84.1	9.2	5.2	1.1	-	0.4	6429	100.0

Source: Department of Census and Statistics

Note: NS[□] - Not Stated

* Statistics given here are only for the affected DS divisions

** Damaged – Completely damaged, Partially damaged (Unusable), Partially damaged (Usable) building units only were considered damaged.