

Table 2.1a: Percentage distribution of *completely damaged housing units* in affected DS divisions* by highest height submerged by sea water : Batticaloe District

Affected DS Division	Highest height submerged (feet)								Total	
	Less than or equal to 5	6 - 7	8 - 10	11 - 20	21 - 30	More than 30	NS [□]	No.	%	
	%	%	%	%	%	%	%			
Koralai Pattu North	15.8	11.3	26.9	42.1	3.6	-	0.3	1307	100.0	
Koralai Pattu	19.0	9.5	4.4	66.7	-	-	0.4	610	100.0	
Koralai Pattu South	28.2	-	28.2	43.6	-	-	-	43	100.0	
Eravur Pattu	30.0	40.0	11.1	18.9	-	-	-	99	100.0	
Manmunai North	9.5	9.1	19.7	51.7	8.0	1.5	0.5	958	100.0	
Kattankudy	22.8	14.7	44.9	16.3	-	-	1.3	505	100.0	
Manmunai Pattu	38.9	26.8	20.2	13.1	0.2	0.2	0.6	633	100.0	
Manmunai South & Eruvilpattu	12.2	13.0	42.2	31.8	0.5	0.1	0.2	1332	100.0	
Total	16.1	12.7	28.0	39.4	3.0	0.4	0.4	5487	100.0	

Note: NS[□] - Not Stated

* Statistics given here are only for the affected DS divisions

** Damaged – Completely damaged, Partially damaged (Unusable), Partially damaged (Usable) building units only were considered damaged.