

Table 8.1: Percentage distribution of buildings other than housing Units damaged\*\* in affected DS division\* by type of Damage:Batticaloe District

Affected DS Division	Type of damage				
	Completely damaged	Partially damaged (Unusable)	Partially damaged (Usable)	Total No. of buildings other than housing units damaged**	
	%	%	%	No.	%
Koralai Pattu North	68.8	10.2	21.0	222	100.0
Koralai pattu	50.0	15.5	34.5	97	100.0
Koralai Pattu South	87.0	4.3	8.7	23	100.0
Eravur Pattu	71.6	-	28.4	74	100.0
Manmunai North	39.4	10.4	50.2	283	100.0
Kattankudy	58.0	5.4	36.6	115	100.0
Manmunai Pattu	40.7	13.5	45.8	110	100.0
Manmunai South & Eruvilpattu	40.8	8.2	51.0	255	100.0
<b>Total</b>	<b>50.4</b>	<b>9.3</b>	<b>40.3</b>	<b>1179</b>	<b>100.0</b>

Source: Department of Census and Statistics

Note: NS<sup>o</sup> - Not Stated

\* Statistics given here are only for the affected DS divisions

\*\* Damaged – Completely damaged, Partially damaged (Unusable), Partially damaged (Usable) building units only were considered damaged.