

**Table 1.4 : Distribution of damaged housing units in the affected GN divisions by type of damage and distance to the sea
: Colombo DS Division of Colombo District**

Affected GN Division	Completely Damaged				Partially damaged (Unusable)				Partially damaged (Usable)				Total			
	Within or on the 100m boundary line	Outside the 100m boundary line	Not Identified	Total	Within or on the 100m boundary line	Outside the 100m boundary line	Not Identified	Total	Within or on the 100m boundary line	Outside the 100m boundary line	Not Identified	Total	Within or on the 100m boundary line	Outside the 100m boundary line	Not Identified	Total
Sammanthranapura	6	0	0	6	7	1	0	8	116	14	0	130	129	15	0	144
Mattakkuliya	39	2	0	41	17	8	0	25	135	56	0	191	191	66	0	257
Modara	77	0	0	77	34	0	0	34	68	4	0	72	179	4	0	183
Aluth Mawatha	8	1	0	9	6	0	0	6	40	0	0	40	54	1	0	55
Lunupokuna	29	0	0	29	15	0	0	15	72	0	0	72	116	0	0	116
D.S. Div. Total	159	3	0	162	79	9	0	88	431	74	0	505	669	86	0	755

Source: Department of Census and Statistics