

**Table 1.8 : Distribution of damaged housing units in the affected GN divisions by type of damage and distance to the sea
: Moratuwa DS Division of Colombo District**

Affected GN Division	Completely Damaged				Partially damaged (Unusable)				Partially damaged (Usable)				Total			
	Within or on the 100m boundary line	Outside the 100m boundary line	Not Identified	Total	Within or on the 100m boundary line	Outside the 100m boundary line	Not Identified	Total	Within or on the 100m boundary line	Outside the 100m boundary line	Not Identified	Total	Within or on the 100m boundary line	Outside the 100m boundary line	Not Identified	Total
Angulana North	82	0	0	82	50	0	0	50	172	0	0	172	304	0	0	304
Angulana South	121	0	0	121	24	0	0	24	100	0	0	100	245	0	0	245
Uyana North	31	0	0	31	12	0	0	12	115	1	0	116	158	1	0	159
Uyana South	41	0	0	41	17	0	0	17	97	0	0	97	155	0	0	155
Uswatta	107	1	0	108	19	0	0	19	104	0	0	104	230	1	0	231
Moratuwella South	59	1	0	60	13	0	0	13	48	1	0	49	120	2	0	122
Moratuwella West	183	0	0	183	28	0	0	28	192	6	0	198	403	6	0	409
Koralawella North	155	1	0	156	31	0	0	31	177	0	0	177	363	1	0	364
Koralawella West	85	0	0	85	14	0	0	14	74	0	0	74	173	0	0	173
Koralawella South	126	0	0	126	3	0	0	3	14	0	0	14	143	0	0	143
Katukurunda North	174	35	0	209	23	0	0	23	84	22	0	106	281	57	0	338
Katukurunda South	250	4	0	254	16	1	0	17	68	19	0	87	334	24	0	358
Egodauyana North	290	21	0	311	52	10	0	62	69	132	0	201	411	163	0	574
Egodauyana Central	209	27	0	236	14	3	0	17	87	90	0	177	310	120	0	430
Egodauyana South	438	90	1	529	41	47	0	88	53	375	0	428	532	512	1	1045
D.S. Div. Total	2351	180	1	2532	357	61	0	418	1454	646	0	2100	4162	887	1	5050

Source: Department of Census and Statistics.