

Table 1.2: Percentage distribution of housing units surveyed and total housing units listed by type of damage in affected DS divisions : Galle District

Affected DS Division	Percentage of Housing Units Surveyed			%	Total Number of Damaged Housing Units Listed
	Completely Damaged	Partially Damaged (Unusable)	Partially Damaged (Usable)		
Benthota	13.0	2.2	84.8	100.0	46
Balapitiya	34.7	7.8	57.5	100.0	2574
Ambalangoda	57.8	4.4	37.8	100.0	595
Hikkaduwa	42.0	8.4	49.6	100.0	5696
Galle Four Gravets	34.0	11.9	54.1	100.0	2066
Habaraduwa	32.8	9.7	57.5	100.0	1668
Total	38.6	8.8	52.6	100.0	12645

Source: Department of Census and Statistics