

Table 1.5: Distribution of damaged housing units in the affected GN divisions by type of damage and distance to the sea : Balapitiya DS Division of Galle District

Affected GN Division	Completely Damaged				Partially damaged (Unusable)				Partially damaged (Usable)				Total			
	Within or on the 100m boundary line	Outside the 100m boundary line	Not Identified	Total	Within or on the 100m boundary line	Outside the 100m boundary line	Not Identified	Total	Within or on the 100m boundary line	Outside the 100m boundary line	Not Identified	Total	Within or on the 100m boundary line	Outside the 100m boundary line	Not Identified	Total
Duwemodara	18	26	0	44	6	10	0	16	21	44	4	69	45	80	4	129
Nape	0	7	0	7	0	6	0	6	0	42	0	42	0	55	0	55
Kudagodagama	0	0	0	0	0	0	0	0	0	11	0	11	0	11	0	11
Hegalla Piyagama	0	5	0	5	0	10	0	10	0	57	0	57	0	72	0	72
Godapitiya	0	1	0	1	0	2	0	2	0	10	0	10	0	13	0	13
Kosgoda	40	154	8	202	3	20	1	24	1	139	0	140	44	313	9	366
Ahungalla	51	22	2	75	3	5	0	8	27	93	3	123	81	120	5	206
Middaramulla	0	4	0	4	0	9	0	9	0	82	0	82	0	95	0	95
Makumbura	0	0	0	0	0	0	0	0	0	9	0	9	0	9	0	9
Wathuregama	11	13	0	24	1	10	0	11	6	46	1	53	18	69	1	88
Wellabada	75	64	1	140	3	19	0	22	7	90	1	98	85	173	2	260
Pathegamgoda	0	11	0	11	0	0	0	0	0	84	0	84	0	95	0	95
Weliwathugoda	0	0	0	0	0	0	0	0	0	35	0	35	0	35	0	35
Brahmanawatta North	62	96	0	158	3	40	2	45	3	268	0	271	68	404	2	474
Brahmanawatta South	101	43	0	144	6	6	0	12	32	120	1	153	139	169	1	309
Elathota	0	3	0	3	0	2	0	2	0	60	0	60	0	65	0	65
Balapitiya	12	16	0	28	4	5	0	9	15	78	0	93	31	99	0	130
Berathuduwa	1	0	0	1	4	0	0	4	10	1	0	11	15	1	0	16
Randombe North	6	1	0	7	2	0	0	2	8	1	0	9	16	2	0	18
Randombe South	34	4	0	38	5	4	0	9	34	10	1	45	73	18	1	92
Walagedara	2	0	0	2	10	0	0	10	24	0	0	24	36	0	0	36
D.S. Div. Total	413	470	11	894	50	148	3	201	188	1280	11	1479	651	1898	25	2574

Source: Department of Census and Statistics.