

Table 1.8: Distribution of damaged housing units in the affected GN divisions by type of damage and distance to the sea : Galle four Gravets DS Division of Galle District.

Affected GN Division	Completely Damaged				Partially damaged (Unusable)				Partially damaged (Usable)				Total			
	Within or on the 100m boundary line	Outside the 100m boundary line	Not Identified	Total	Within or on the 100m boundary line	Outside the 100m boundary line	Not Identified	Total	Within or on the 100m boundary line	Outside the 100m boundary line	Not Identified	Total	Within or on the 100m boundary line	Outside the 100m boundary line	Not Identified	Total
Welipitimodara	0	1	0	1	0	1	0	1	0	12	0	12	0	14	0	14
Ginthota West	19	0	0	19	12	0	0	12	38	2	0	40	69	2	0	71
Ginthota East	13	3	0	16	4	0	0	4	17	7	1	25	34	10	1	45
Bope West	0	0	0	0	0	1	0	1	0	0	0	0	0	1	0	1
Siyambalagahawatta	44	5	5	54	3	2	0	5	8	12	1	21	55	19	6	80
Dadalla East	0	0	0	0	0	2	0	2	0	3	0	3	0	5	0	5
Dadalla West	31	0	0	31	7	0	0	7	23	2	0	25	61	2	0	63
Walawwatta	8	17	1	26	1	1	0	2	10	17	0	27	19	35	1	55
Kumbalawella South	0	0	0	0	0	0	0	0	0	4	0	4	0	4	0	4
Mahamodara	61	0	3	64	18	7	5	30	108	42	16	166	187	49	24	260
Kandewatta	0	0	0	0	0	0	0	0	0	12	0	12	0	12	0	12
Makuluwa	0	0	0	0	0	2	0	2	0	23	0	23	0	25	0	25
Pettigalawatta	39	27	5	71	23	9	1	33	19	59	1	79	81	95	7	183
Thalapitiya	0	19	0	19	0	14	0	14	0	89	0	89	0	122	0	122
Weliwatta	1	1	0	2	2	2	0	4	4	17	0	21	7	20	0	27
Minuwangoda	0	0	0	0	0	2	0	2	0	8	0	8	0	10	0	10
Kaluwella	19	0	0	19	8	0	0	8	74	1	12	87	101	1	12	114
Magalla	16	40	0	56	4	29	0	33	0	164	1	165	20	233	1	254
Dewathura	3	18	0	21	0	0	0	0	0	36	0	36	3	54	0	57
Dewata	101	16	0	117	13	17	0	30	25	29	0	54	139	62	0	201
Cheena Koratuwa	22	6	0	28	0	19	0	19	1	98	0	99	23	123	0	146
Katugoda	117	41	1	159	17	20	0	37	24	97	0	121	158	158	1	317
D.S. Div. Total	494	194	15	703	112	128	6	246	351	734	32	1117	957	1056	53	2066

Source: Department of Census and Statistics.