

Table 2.2a: Percentage distribution of *completely damaged housing units* in affected DS divisions* by condition of the toilet facility : Galle District

Affected DS Division	Condition of the toilet facility					
	Damaged	Not damaged	No latrine	NS [□]	Total	
	%	%	%	%	No.	%
Bentota	16.7	50.0	33.3	-	6	100.0
Balapitiya	48.6	13.5	37.6	0.3	894	100.0
Ambalangoda	59.0	3.0	38.0	-	344	100.0
Hikkaduwa	65.4	8.6	25.8	0.2	2391	100.0
Galle Four Gravets	68.8	12.0	18.9	0.3	703	100.0
Habaraduwa	64.6	12.0	23.1	0.3	547	100.0
Total	62.2	10.1	27.5	0.2	4885	100.0

Source: Department of Census and Statistics

Table 2.2b: Percentage distribution of *partially damaged housing units (unusable)* in affected DS divisions* by condition of the toilet facility :Galle District

Affected DS Division	Condition of the toilet facility					
	Damaged	Not damaged	No latrine	NS [□]	Total	
	%	%	%	%	No.	%
Bentota	-	100.0	-	-	1	100.0
Balapitiya	61.5	23.1	15.4	-	201	100.0
Ambalangoda	46.2	53.8	-	-	26	100.0
Hikkaduwa	55.6	25.2	18.9	0.3	479	100.0
Galle Four Gravets	62.0	28.8	8.7	0.5	246	100.0
Habaraduwa	56.8	27.7	15.5	-	162	100.0
Total	58.0	26.9	14.9	0.2	1115	100.0

Source: Department of Census and Statistics

Table 2.2c: Percentage distribution of *partially damaged housing units (usable)* in affected DS divisions* by condition of the toilet facility: Galle District

Affected DS Division	Condition of the toilet facility					
	Damaged	Not damaged	No latrine	NS [□]	Total	
	%	%	%	%	No.	%
Bentota	40.6	53.1	6.3	-	39	100.0
Balapitiya	32.4	56.1	11.4	0.1	1479	100.0
Ambalangoda	40.7	52.6	6.2	0.5	225	100.0
Hikkaduwa	33.6	54.0	11.9	0.5	2826	100.0
Galle Four Gravets	41.4	51.1	7.1	0.4	1117	100.0
Habaraduwa	36.9	53.3	9.7	0.1	959	100.0
Total	35.3	53.9	10.5	0.3	6645	100.0

Source: Department of Census and Statistics

Note: NS[□] - Not Stated

* Statistics given here are only for the affected DS divisions

** Damaged – Completely damaged, Partially damaged (Unusable), Partially damaged (Usable) building units only were considered damaged.