

Table 2.6: Percentage distribution of the *damaged** housing units* in the affected DS divisions* by number of rooms in the unit: Galle District

Affected DS Division	Percentage of housing units by number of rooms					
	1 - 3	4 - 6	More than 6	NS [□]	Total	
	%	%	%	%	No.	%
Bentota	56.4	41.0	2.6	-	46	100.0
Balapitiya	44.9	50.1	4.9	0.1	2574	100.0
Ambalangoda	60.5	35.8	3.5	0.2	595	100.0
Hikkaduwa	45.3	48.9	5.5	0.3	5696	100.0
Galle Four Gravets	62.2	33.2	4.2	0.4	2066	100.0
Habaraduwa	64.4	31.4	2.7	1.5	1668	100.0
Total	51.4	43.5	4.7	0.4	12645	100.0

Source: Department of Census and Statistics

Table 2.7: Percentage distribution of the *damaged** housing units* in the affected DS divisions* By floor area of the housing unit: Galle District

Affected DS Division	Floor area of the housing unit (Sq.feet)					
	< 100	100 - 999	1000 - 9999	NS [□]	Total	
	%	%	%	%	No.	%
Bentota	2.6	71.8	25.6	-	46	100.0
Balapitiya	1.3	67.0	30.3	1.4	2574	100.0
Ambalangoda	1.4	77.8	20.4	0.4	595	100.0
Hikkaduwa	2.9	71.4	24.2	1.5	5696	100.0
Galle Four Gravets	4.8	74.1	20.6	0.5	2066	100.0
Habaraduwa	5.7	69.7	23.7	0.9	1668	100.0
Total	3.2	71.0	24.6	1.2	12645	100.0

Source: Department of Census and Statistics

Note: NS[□] - Not Stated

* Statistics given here are only for the affected DS divisions

** Damaged – Completely damaged, Partially damaged (Unusable), Partially damaged (Usable) building units only were considered damaged.