

**Table 1.3: Distribution of damaged housing units in the affected DS divisions by type of damage and distance to the sea : Gampaha District**

Affected DS Division	Completely Damaged				Partially damaged (Unusable)				Partially damaged (Usable)				Total			
	Within or on the 100m boundary line	Outside the 100m boundary line	Not Identified	Total	Within or on the 100m boundary line	Outside the 100m boundary line	Not Identified	Total	Within or on the 100m boundary line	Outside the 100m boundary line	Not Identified	Total	Within or on the 100m boundary line	Outside the 100m boundary line	Not Identified	Total
Negombo	249	13	0	262	44	12	0	56	275	86	0	361	568	111	0	679
Wattala	12	16	0	28	16	15	0	31	47	221	0	268	75	252	0	327
<b>District Total</b>	<b>261</b>	<b>29</b>	<b>0</b>	<b>290</b>	<b>60</b>	<b>27</b>	<b>0</b>	<b>87</b>	<b>322</b>	<b>307</b>	<b>0</b>	<b>629</b>	<b>643</b>	<b>363</b>	<b>0</b>	<b>1006</b>

Source: Department of Census and Statistics