

Table 2.4a: Percentage distribution of *completely damaged housing units* which did not have drinking water facilities after Tsunami by reason for not having water by affected DS divisions* of : Gampaha District

Affected DS Division	Main reason for not having drinking facilities					
	Polluted Well	Main line destroyed	Other	NS [□]	Total	
	%	%	%	%	No.	%
Negombo	3.1	50.0	6.3	40.6	262	100.0
Wattala	-	33.3	-	66.7	28	100.0
Total	2.9	48.5	5.7	42.9	290	100.0

Source: Department of Census and Statistics

Table 2.4b: Percentage distribution of *partially damaged housing units (unusable)*, which did not have drinking water facilities after Tsunami by reason for not having water by affected DS divisions* of : Gampaha District

Affected DS Division	Main reason for not having drinking facilities					
	Polluted Well	Main line destroyed	Other	NS [□]	Total	
	%	%	%	%	No.	%
Negombo	-	33.3	33.3	33.4	56	100.0
Wattala	-	33.3	33.3	33.4	31	100.0
Total	-	33.3	33.3	33.4	87	100.0

Source: Department of Census and Statistics

Table 2.4c: Percentage distribution of *partially damaged housing units (usable)*, which did not have drinking water facilities after Tsunami by reason for not having water by affected DS divisions* of : Gampaha District

Affected DS Division	Main reason for not having drinking facilities					
	Polluted Well	Main line destroyed	Other	NS [□]	Total	
	%	%	%	%	No.	%
Negombo	-	14.3	42.9	42.8	361	100.0
Wattala	66.7	33.3	-	-	268	100.0
Total	20.0	20.0	30.0	30.0	629	100.0

Source: Department of Census and Statistics

Note: NS[□] - Not Stated

* Statistics given here are only for the affected DS divisions

** Damaged – Completely damaged, Partially damaged (Unusable), Partially damaged (Usable) building units only were considered damaged.