

**Table 1.3 : Distribution of damaged housing units in the affected DS divisions by type of damage and distance to the sea : Kalutara District**

Affected DS Division	Completely Damaged				Partially damaged (Unusable)				Partially damaged (Usable)				Total			
	Within or on the 100m boundary line	Outside the 100m boundary line	Not Identified	Total	Within or on the 100m boundary line	Outside the 100m boundary line	Not Identified	Total	Within or on the 100m boundary line	Outside the 100m boundary line	Not Identified	Total	Within or on the 100m boundary line	Outside the 100m boundary line	Not Identified	Total
Panadura	675	203	0	878	74	91	0	165	370	993	0	1363	1119	1287	0	2406
Kalutara	498	158	0	656	115	90	1	206	443	920	3	1366	1056	1168	4	2228
Beruwala	538	305	9	852	43	94	4	141	219	835	16	1070	800	1234	29	2063
<b>District Total</b>	<b>1711</b>	<b>666</b>	<b>9</b>	<b>2386</b>	<b>232</b>	<b>275</b>	<b>5</b>	<b>512</b>	<b>1032</b>	<b>2748</b>	<b>19</b>	<b>3799</b>	<b>2975</b>	<b>3689</b>	<b>33</b>	<b>6697</b>

Source: Department of Census and Statistics