

Table 2.2a: Percentage distribution of *completely damaged housing units* in affected DS divisions* by condition of the toilet facilities: Kalutara District

Affected DS Division	Condition of the toilet facility					
	Damaged	Not damaged	No latrine	NS [□]	Total	
	%	%	%	%	No.	%
Panadura	50.1	13.4	36.2	0.3	878	100.0
Kalutara	61.1	8.8	30.1	-	656	100.0
Beruwala	76.5	9.8	13.7	-	852	100.0
Total	62.3	10.8	26.8	0.1	2386	100.0

Source: Department of Census and Statistics

Table 2.2b: Percentage distribution of *partially damaged housing units (unusable)* in affected DS divisions* by condition of the toilet facilities : Kalutara District

Affected DS Division	Condition of the toilet facility					
	Damaged	Not damaged	No latrine	NS [□]	Total	
	%	%	%	%	No.	%
Panadura	47.8	39.7	12.5	-	165	100.0
Kalutara	49.1	29.7	20.6	0.6	206	100.0
Beruwala	52.2	37.2	9.7	0.9	141	100.0
Total	49.5	34.9	15.1	0.5	512	100.0

Source: Department of Census and Statistics

Table 2.2c: Percentage distribution of *partially damaged housing units (usable)* in affected DS divisions* by condition of the toilet facilities: Kalutara District

Affected DS Division	Condition of the toilet facility					
	Damaged	Not damaged	No latrine	NS [□]	Total	
	%	%	%	%	No.	%
Panadura	28.7	67.0	4.1	0.2	1363	100.0
Kalutara	29.4	56.0	14.2	0.4	1366	100.0
Beruwala	23.8	70.7	5.3	0.2	1070	100.0
Total	27.5	64.2	8.0	0.3	3799	100.0

Source: Department of Census and Statistics

Note: NS[□] - Not Stated

* Statistics given here are only for the affected DS divisions

** Damaged – Completely damaged, Partially damaged (Unusable), Partially damaged (Usable) building units only were considered damaged.