

Table 2.6: Percentage distribution of the *damaged\*\* housing units* in the affected DS divisions\* by number of rooms in the unit: Kalutara District

Affected DS Division	Percentage of housing units by Number of rooms					
	1 - 3	4 - 6	More than 6	NS <sup>□</sup>	Total	
	%	%	%	%	No.	%
Panadura	72.9	25.3	1.4	0.4	2406	100.0
Kalutara	67.1	31.3	1.2	0.4	2228	100.0
Beruwala	47.1	49.0	3.5	0.4	2063	100.0
<b>Total</b>	<b>63.2</b>	<b>34.5</b>	<b>1.9</b>	<b>0.4</b>	<b>6697</b>	<b>100.0</b>

Source: Department of Census and Statistics

Table 2.7: Percentage distribution of the *damaged\*\* housing units* in the affected DS divisions\* By floor area of the housing unit: Kalutara District

Affected DS Division	Percentage of housing units by floor area (Sq. feet)					
	< 100	100-999	1000-9999	NS <sup>□</sup>	Total	
	%	%	%	%	No.	%
Panadura	2.6	72.0	24.1	1.3	2406	100.0
Kalutara	3.1	70.3	23.1	3.5	2228	100.0
Beruwala	0.5	65.5	33.1	0.9	2063	100.0
<b>Total</b>	<b>2.1</b>	<b>69.4</b>	<b>26.6</b>	<b>1.9</b>	<b>6697</b>	<b>100.0</b>

Source: Department of Census and Statistics

Note: NS<sup>□</sup> - Not Stated

\* Statistics given here are only for the affected DS divisions

\*\* Damaged – Completely damaged, Partially damaged (Unusable), Partially damaged (Usable) building units only were considered damaged.