

Table 1.5 : Distribution of damaged housing units in the affected GN divisions by type of damage and distance to the sea : Kandawali DS Division of Killinochchi District

| Affected GN Division | Completely Damaged | | | | Partially damaged (Unusable) | | | | Partially damaged (Usable) | | | | Total | | | |
|------------------------|-------------------------------------|--------------------------------|----------------|-----------|-------------------------------------|--------------------------------|----------------|----------|-------------------------------------|--------------------------------|----------------|----------|-------------------------------------|--------------------------------|----------------|-----------|
| | Within or on the 200m boundary line | Outside the 200m boundary line | Not Identified | Total | Within or on the 200m boundary line | Outside the 200m boundary line | Not Identified | Total | Within or on the 200m boundary line | Outside the 200m boundary line | Not Identified | Total | Within or on the 200m boundary line | Outside the 200m boundary line | Not Identified | Total |
| Elephantpass | 9 | 0 | 0 | 9 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 9 | 0 | 0 | 9 |
| Puliyapokkanai | 6 | 0 | 0 | 6 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 6 | 0 | 0 | 6 |
| D.S. Div. Total | 15 | 0 | 0 | 15 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 15 | 0 | 0 | 15 |

Source: Department of Census and Statistics.