

Table 2.4: Percentage distribution of *completely damaged housing units* which did not have drinking water facility after Tsunami by reason for not having water by affected DS divisions\* of : killinochchi District

Affected DS Division	Main reason for not having drinking water facilities					
	Polluted well	Main line destroyed	Other	NS <sup>□</sup>	Total	
	%	%	%	%	No.	%
Panchchilaipalli	24.6	0.7	74.0	0.7	187	100.0
Kandawali	-	-	100.0	-	15	100.0
Poonakary	20.9	-	77.9	1.2	92	100.0
<b>Total</b>	21.8	0.4	77.0	0.8	<b>294</b>	<b>100.0</b>

Source: Department of Census and Statistics

Note: NS<sup>□</sup> - Not Stated

\* Statistics given here are only for the affected DS divisions

\*\* Damaged – Completely damaged, Partially damaged (Unusable), Partially damaged (Usable) building units only were considered damaged.