

**Table 1.7 : Distribution of damaged housing units in the affected GN divisions by type of damage and distance to the sea : Dickwella DS Division of Matara District**

G.N. Division	Completely Damaged			Partially damaged (unusable)			Partially damaged (usable)			Total		
	Within or on the 100m boundary line	Outside the 100m boundary line	Total	Within or on the 100m boundary line	Outside the 100m boundary line	Total	Within or on the 100m boundary line	Outside the 100m boundary line	Total	Within or on the 100m boundary line	Outside the 100m boundary line	Total
Suduwella	36	16	52	15	10	25	53	39	92	104	65	169
Wattegama South	26	28	54	3	14	17	14	68	82	43	110	153
Dikwella South	22	4	26	7	2	9	14	32	46	43	38	81
Dikwella East	1	1	2	0	3	3	10	9	19	11	13	24
Dodampahala Central	3	0	3	0	0	0	14	3	17	17	3	20
Dodampahala South	4	0	4	5	0	5	10	2	12	19	2	21
Dodampahala East	9	0	9	8	0	8	13	5	18	30	5	35
Kottagoda	35	11	46	25	4	29	79	31	110	139	46	185
GodaUda	8	1	9	0	0	0	5	2	7	13	3	16
Beliwatta	65	2	67	9	6	15	30	18	48	104	26	130
Lunukalapuwa	2	3	5	2	0	2	7	3	10	11	6	17
Bambarenda South	3	0	3	2	0	2	0	1	1	5	1	6
Bambarenda East	0	0	0	0	0	0	0	1	1	0	1	1
Batheegama Central	0	0	0	3	1	4	4	4	8	7	5	12
Batheegama East	24	4	28	6	0	6	21	40	61	51	44	95
Batheegama West	4	0	4	0	0	0	2	0	2	6	0	6
<b>D.S. Div. Total</b>	<b>242</b>	<b>70</b>	<b>312</b>	<b>85</b>	<b>40</b>	<b>125</b>	<b>276</b>	<b>258</b>	<b>534</b>	<b>603</b>	<b>368</b>	<b>971</b>

Source: Department of Census and Statistics.