

Table 2.4a: Percentage distribution of *completely damaged housing units* which did not have drinking water facilities after Tsunami by reason for not having water by affected DS divisions* of : Hambantota District

Affected DS Division	Reason for not having drinking facilities					
	Polluted well	Main line destroyed	Other	NS [□]	Total	
	%	%	%	%	No.	%
Thissamaharamaya	14.6	77.6	4.9	2.9	132	100.0
Hambantota	0.5	81.3	10.7	7.5	549	100.0
Ambalantota	4.2	22.9	66.6	6.3	104	100.0
Tangalle	8.5	72.0	13.6	5.9	433	100.0
Total	4.9	74.6	14.1	6.4	1218	100.0

Source: Department of Census and Statistic

Table 2.4b: Percentage distribution of *partially damaged housing units (unusable)*, which did not have drinking water facility after Tsunami by reason for not having water by affected DS divisions* of :Hambantota District

Affected DS Division	Reason for not having drinking facilities					
	Polluted well	Main line destroyed	Other	NS [□]	Total	
	%	%	%	%	No.	%
Thissamaharamaya	50.0	8.3	41.7	-	26	100.0
Hambantota	-	88.9	7.4	3.7	55	100.0
Ambalantota	-	-	100.0	-	21	100.0
Tangalle	10.0	63.3	21.1	5.6	202	100.0
Total	11.1	60.7	23.8	4.4	304	100.0

Source: Department of Census and Statistics

Table 2.4c: Percentage distribution of *partially damaged housing units (usable)*, which did not have drinking water facility after Tsunami by reason for not having water by affected DS divisions* of Hambantota District

Affected DS Division	Reason for not having drinking facilities					
	Polluted well	Main line destroyed	Other	NS [□]	Total	
	%	%	%	%	No.	%
Thissamaharamaya	66.6	16.7	11.1	5.6	52	100.0
Hambantota	-	82.7	9.6	7.7	178	100.0
Ambalantota	-	25.0	25.0	50.0	65	100.0
Tangalle	12.6	52.9	23.3	11.2	724	100.0
Total	13.6	55.7	20.0	10.7	1019	100.0

Source: Department of Census and Statistics

Note: NS[□] - Not Stated

* Statistics given here are only for the affected DS divisions

** Damaged – Completely damaged, Partially damaged (Unusable), Partially damaged (Usable) building units only were considered damaged.